

Fill Rate Data ARDSA Catch Basin Cleaning MS4

In 2016 the Municipal Street Maintenance Division began our fill rate data collection program. Our contractor Alaska Stormwater Maintenance cleaned every catch basin South of Grid 2329. They gathered the material depth and sump depth of each catch basin. Prior to 2016 back to 2011 Street Maintenance had been inspecting each catch basin every year and if material was within 6 inches of the outfall the catch basin was cleaned. No material depths were recorded.

Alaska Stormwater cleaned 1837 basins in 2016, in 2017 all of those basins were inspected and material depth was measured. If the material was within 6 inches of the outfall the basin was cleaned. There were 37 basins in need of cleaning in 2017. In 2018 the process was repeated and 330 basins were in need of cleaning. 15 of the basins that needed cleaned in 2017 were the same basins that needed cleaned in 2018. These basins will be inspected again in 2019.

In 2017 Alaska Stormwater cleaned all catch basins between Dowling rd. and Dimond Blvd. Material depth and sump depth were measured. These basins were inspected in 2018 and material depth was measured, if material depth was within 6 inches of the outfall the basin was cleaned. In 2017 Alaska Storm water cleaned 1740 basins, in 2018, 262 of these needed to be cleaned. These basins will be inspected again in 2019.

In 2017 Municipal crews cleaned all catch basins north of 15th Ave., material depth and sump depth were measured. These basins were inspected in 2018 and material depth was measure in material depth was within 6 inches of the outfall the basin was cleaned. In 2017 MOA crews cleaned 1720 basins, in 2018, 357 needed to be cleaned. These basins will be inspected again in 2019.

In 2018 MOA crews and Alaska Stormwater cleaned all catch basins between 15th and Dowling; material depth and sump depth were measured and recorded. These basins will be inspected in 2019 and material depth will be measured. If material depth is within 6 inches of the outfall the basin will be cleaned. In 2018, 3637 basins were cleaned.

MOA crews spend approximately 700-800 labor hours every season just inspecting whether cleaning is needed and usually find approximately ¼ of the catch basins need cleaning but they are scattered all across the city. Our findings also conclude that there are a number of basins that are in need of cleaning every year. Many of these basins have a very small sediment depth and less than 8 inches of sump which would trigger a cleaning with the current inspection guidelines; new specifications of those guidelines will need to be created to bring the 'needed to be cleaned' number down to a realistic level. Our goal is to identify which catch basins in ARDSA need to be cleaned every year and which ones need to be cleaned every other year; with the end result of having the entire city on a 4 year cleaning schedule. By cleaning annual and bi-annual catch basins, then being able clean ¼ of the rest of the catch basins every season it will save labor hours by not inspecting 10,000+ catch basins every season. A cleaning crew is much more efficient when they can grid work an area cleaning all the drains. If we know which drains fill annually and bi-annually, Street Maintenance feels we can eliminate annual inspections.

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32329004	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32329004		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32329008	401	NA			6"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32329008		Catch Basin			6-8			6/20/17	No			inspected_ok	6/20/17	
32329020	507	NA			4"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32329020		Manhole	Type 1	12-14"	12-14	12	Good	08/26/17	Yes	No		clean_complete	08/26/17	
32329041	401	NA			2"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32329041		Catch Basin	Type 1	14-16"	0-2"	12	Good	08/26/17	Yes	No		clean_complete	08/26/17	
32329078	401	Installed: 2016			2"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32329078		Catch Basin	Type 1	16-18"	0-2"	15	Good	08/26/17	Yes	No		clean_complete	08/26/17	Installed: 2016
32330017	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330017		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330018	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330018		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330019	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330019		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330020	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330020		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330021	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330021		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330029	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330029		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330034	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330034		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330035	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330035		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330036	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330036		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330037	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330037		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330069	507	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330069		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32330088	507	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330088		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330091	507	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330091		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330105	507	NA			2"		Good		No	No	Bennett, Steve	inspected_ok	06/22/2018	
32330105		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32330122	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	Can not find
32330122		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330133	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330133		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330192	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330192		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330193	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330193		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330194	401	NA			None				No		Van Fleet, Myhi	inspected_ok	06/22/2018	
32330194		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330195	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330195		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330198	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330198		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330199	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330199		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330200	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330200		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330203	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32330203		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330204	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330204		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330205	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330205		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330209	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330209		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330210	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330210		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330211	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330211		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330212	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330212		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330213	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330213		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330214	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330214		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	Broken drain lid
32330215	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330215		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330221	507	NA			6"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330221		Manhole			4-6			6/20/17	No			inspected_ok	6/20/17	
32330230	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330230		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330231	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330231		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330232	401	NA			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330232		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330233	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330233		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330235	401	NA			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330235		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32330245	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330245		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330246	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330246		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330248	401	NA					Good		No	No	Van Fleet, Myhi	inspected_ok	08/27/2018	
32330248		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330249	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330249		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330250	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330250		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330253	507	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330253		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330259	507	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330259		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330262	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330262		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330263	401	NA			6"	12	Good		Yes	No	Van Fleet, Myhi	clean_complete	07/10/2018	
32330263		Catch Basin			6-8			6/20/17	Yes		62187	clean_complete	07/20/17	
32330265	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330265		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330266	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330266		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330277	507	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330277		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330523	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330523		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32330525	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330525		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32330566	507	R142425			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32330566		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331010	507	NA			2"				No	No	Bennett, Steve	inspected_ok	06/22/2018	
32331010		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331011	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331011		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331012	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331012		Catch Basin			4-6			6/20/17	Yes		62187	clean_complete	07/20/17	
32331013	401	NA			4"	12	Good		Yes	No	Van Fleet, Myhi	clean_complete	07/10/2018	
32331013		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331014	401	NA			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331014		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331015	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331015		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32331016	401	NA					Good		No	No	Van Fleet, Myhi	inspected_ok	08/27/2018	
32331016		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32331017	507	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331017		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331018	401	NA			5"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331018		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331019	401	NA			6"	12	Good		Yes	No	Van Fleet, Myhi	clean_complete	07/10/2018	
32331019		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331020	401	NA			7"	12	Good		Yes	No	Weatherby, Marcus	clean_complete	07/10/2018	
32331020		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32331022	401	NA					Good		No	No	Van Fleet, Myhi	inspected_ok	08/27/2018	
32331023	507	NA					Good		No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331023		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32331024	401	NA							No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331024		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32331142	401	NA			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331142		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32331144	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32331144		Catch Basin			0-2"			6/21/17	Yes		62187	clean_complete	07/20/17	
32332012	507	NA			4"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32332015	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332015		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332035	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332035		Catch Basin			2-4			6/21/17	No		62187	clean_complete	07/20/17	
32332039	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332039		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332044	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332044		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332045	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332045		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332046	401	NA			12"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/26/2018	
32332047	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332047		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332048	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332048		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332049	507	NA			Greater than 24"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/26/2018	
32332049		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332050	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332050		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32332051	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332051		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32332052	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32332052		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333001	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333001		Catch Basin			2-4			6/21/17	No		62187	clean_complete	07/20/17	Dry well
32333002	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333002		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333003	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333003		Catch Basin			0-2"				No			inspected_ok		
32333004	401	NA			4"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32333004		Catch Basin								Yes				Witches hat. Not inspected
32333005	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333005		Catch Basin			2-4			07/20/17			62187	clean_complete	07/20/17	
32333006	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333006		Catch Basin			2-4			6/21/17	Yes		62187	clean_complete	07/20/17	Dry well
32333008	507	NA			18"	36	Immediate		Yes	No	Lyman, Brian	clean_complete	06/26/2018	Bottom 3' of structure is rooted away!
32333008		Manhole			4-6			6/21/17	Yes			clean	6/21/17	
32333009	507	NA			24"	36	Immediate		Yes	No	Lyman, Brian	clean_complete	06/26/2018	structure needs help!
32333009		Manhole			8-10			6/21/17	Yes			clean	6/21/17	
32333010	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333010		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333011	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333011		Catch Basin			0-2"				No			inspected_ok		
32333015	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333015		Catch Basin			0-2"				No			inspected_ok		
32333016	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333016		Catch Basin			0-2"				No			inspected_ok		
32333020	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333020		Catch Basin			0-2"				No			inspected_ok		
32333022	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333022		Catch Basin			0-2"				No			inspected_ok		
32333033	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333033		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333046	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333046		Catch Basin			0-2"				No			inspected_ok		
32333053	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333053		Catch Basin			0-2"				No			inspected_ok		
32333054	401	6			10"	12	Good		Yes	No	Contractor	clean_complete	05/14/2018	
32333054		Catch Basin			4-6				Yes			clean		
32333055	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333055		Manhole			0-2"				No			inspected_ok		
32333056	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333056		Catch Basin			0-2"				No			inspected_ok		
32333058	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333058		Manhole			0-2"				No			inspected_ok		
32333059	401	NA			8"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32333059		Catch Basin								Yes				Witches hat. Not inspected
32333060	507	NA		7"	6"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333060		Manhole			6-8				No			inspected_ok		
32333061	507	NA		10"	4"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333061		Manhole			0-2"				No			inspected_ok		
32333063	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333063		Catch Basin			0-2"				No			inspected_ok		
32333064	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333064		Catch Basin			0-2"				No			inspected_ok		
32333065	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333065		Manhole								Yes				Witches hat. Not inspected
32333072	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32333072		Catch Basin								Yes				Witches hat. Not inspected
32333079	401	NA		18"	4"	12	Good		Yes	No	Amell, Mark	clean_complete	10/19/2018	
32333080	507	NA		7"	1"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333080		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333081	507	NA		7"	1"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333081		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333083	507	NA		7"	1"				Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333083		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333084	401	NA		8"	1"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333084		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333087	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333087		Manhole			0-2"				No			inspected_ok		
32333088	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333088		Catch Basin												Does not exist (abandoned?)
32333093	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333093		Manhole			0-2"				No			inspected_ok		
32333098	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333098		Catch Basin			0-2"				No			inspected_ok		
32333102	507	NA			3"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32333102		Manhole								Yes				Witches hat. Not inspected
32333103	401	NA			None		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333103		Catch Basin			0-2"				No			inspected_ok		
32333104	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333104		Manhole			0-2"				No			inspected_ok		
32333105	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333105		Catch Basin			0-2"				No			inspected_ok		
32333108	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333108		Catch Basin			0-2"				No			inspected_ok		
32333109	507	NA		Less than 6"	5"	12	Good		Yes	No	Dunaho, Milton	clean_complete	09/19/2018	Remove Witches hat
32333109		Manhole								Yes				Witches hat. Not inspected
32333112	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333112		Catch Basin												Couldn't find (non-existent?)
32333113	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333113		Catch Basin												Couldn't find(non-existent?)
32333140	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333140		Catch Basin			0-2"				No			inspected_ok		
32333141	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333141		Catch Basin			0-2"				No			inspected_ok		
32333142	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333142		Manhole			0-2"				No			inspected_ok		
32333143	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333143		Manhole			0-2"				No			inspected_ok		
32333144	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333144		Catch Basin			0-2"				No			inspected_ok		
32333145	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333145		Manhole			0-2"				No			inspected_ok		
32333148	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333148		Catch Basin			0-2"				No			inspected_ok		
32333149	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333149		Catch Basin			0-2"				No			inspected_ok		
32333150	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333150		Catch Basin			0-2"				No			inspected_ok		
32333151	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333151		Manhole			0-2"				No			inspected_ok		
32333152	507	NA		12"	3"	12	Good		No		Amell, Mark	clean_complete	10/19/2018	
32333152		Manhole			0-2"				No			inspected_ok		Catchbasin Manhole covered by boulders and dirt. Needs uncovered
32333153	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32333153		Catch Basin			0-2"				No			inspected_ok		
32333154	401	NA		8"	1"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32333154		Catch Basin			0-2"				No			inspected_ok		
32333155	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333155		Manhole			0-2"				No			inspected_ok		
32333156	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333156		Manhole			0-2"				No			inspected_ok		
32333158	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333158		Manhole			0-2"				No			inspected_ok		
32333160	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333160		Catch Basin			0-2"				No			inspected_ok		
32333170	401	NA		8"	3"	12	Good		Yes		Bell, Brian, Brian	inspected_ok	08/29/2018	
32333170		Catch Basin			0-2"				No			inspected_ok		
32333206	507	NA		8"	6"	18	Good		Yes	No	Dunaho, Milton	clean_complete	09/20/2018	
32333206		Manhole			6-8				No			inspected_ok		
32333207	507	NA		8"	3"	12	Good		Yes		Bell, Brian, Brian	inspected_ok	08/29/2018	
32333207		Manhole			0-2"				No			inspected_ok		
32333226	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333226		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32333228	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333228		Manhole			0-2"				No			inspected_ok		
32333229	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333229		Catch Basin			0-2"				No			inspected_ok		
32333230	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32333230		Catch Basin			0-2"				No			inspected_ok		
32333231	507	NA			18"	12	Good		Yes	No	Banie, Harold	clean_complete	07/25/2018	
32333231		Manhole			6-8				No			inspected_ok		
32333255	507	10			18"	12	Good		Yes	No	Contractor	clean_complete	05/14/2018	
32333255		Manhole			0-2"				Yes			clean		
32334005	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334005		Catch Basin			0-2"				No			inspected_ok		
32334006	401	NA			8"		Immediate		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/25/2018	Collapsing around structure
32334006		Catch Basin			0-2"				No			inspected_ok		
32334007	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334007		Catch Basin			0-2"				No			inspected_ok		
32334008	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334008		Catch Basin			0-2"				No			inspected_ok		
32334035	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334035		Catch Basin												Witches hat on it
32334037	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334037		Catch Basin			0-2"				No			inspected_ok		
32334054	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334054		Catch Basin			0-2"				No			inspected_ok		
32334055	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334055		Manhole			0-2"				No			inspected_ok		
32334061	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334061		Catch Basin			0-2"				No			inspected_ok		
32334062	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334062		Catch Basin			0-2"				No			inspected_ok		
32334084	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334084		Catch Basin			0-2"				No			inspected_ok		
32334101	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334101		Catch Basin			0-2"				No			inspected_ok		
32334102	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334102		Catch Basin			0-2"				No			inspected_ok		
32334104	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334104		Catch Basin			0-2"				No			inspected_ok		

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32334107	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334107		Catch Basin			0-2"				No			inspected_ok		
32334108	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334108		Manhole			0-2"				No			inspected_ok		
32334112	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334112		Catch Basin			0-2"				No			inspected_ok		
32334113	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334113		Catch Basin			0-2"				No			inspected_ok		
32334114	401	NA			12"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32334114		Catch Basin			0-2"				No			inspected_ok		
32334119	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334119		Manhole			0-2"				No			inspected_ok		
32334120	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334120		Catch Basin			0-2"				No			inspected_ok		
32334123	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334123		Manhole												
32334125	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334125		Catch Basin			0-2"				No			inspected_ok		
32334126	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334126		Catch Basin			0-2"				No			inspected_ok		
32334129	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334129		Manhole			0-2"				No			inspected_ok		
32334133	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334133		Catch Basin			0-2"				No			inspected_ok		
32334136	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334136		Catch Basin			0-2"				No			inspected_ok		
32334137	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334137		Catch Basin			0-2"				No			inspected_ok		
32334138	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334138		Catch Basin			0-2"				No			inspected_ok		
32334139	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334139		Catch Basin			0-2"				No			inspected_ok		
32334140	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334140		Manhole			0-2"				No			inspected_ok		
32334141	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334141		Manhole			0-2"				No			inspected_ok		
32334142	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334142		Catch Basin			0-2"				No			inspected_ok		
32334147	507	NA			8"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334147		Manhole			0-2"				No			inspected_ok		
32334149	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334149		Catch Basin	Type 1	8-10"	0-2"	12			No			inspected_ok		
32334150	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334150		Catch Basin												
32334151	401	6			10"	12	Good		Yes	No	Contractor	clean_complete	05/14/2018	
32334151		Catch Basin	Type 1	8-10"	4-6	12						clean		
32334152	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334152		Catch Basin	Type 1	8-10"	0-2"	12						inspected_ok		
32334153	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334153		Manhole			0-2"				No			inspected_ok		
32334155	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334155		Catch Basin			0-2"				No			inspected_ok		
32334156	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334156		Catch Basin			0-2"				No			inspected_ok		
32334157	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334157		Catch Basin			0-2"				No			inspected_ok		
32334158	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32334158		Catch Basin			0-2"				No			inspected_ok		
32334159	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334159		Catch Basin			0-2"				No			inspected_ok		
32334160	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334160		Catch Basin			0-2"				No			inspected_ok		
32334162	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334162		Catch Basin			0-2"				No			inspected_ok		
32334163	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334163		Manhole			0-2"				No			inspected_ok		
32334164	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334164		Manhole			0-2"				No			inspected_ok		
32334165	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334165		Catch Basin			0-2"				No			inspected_ok		
32334167		Manhole			0-2"				No			inspected_ok		
32334168	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334168		Catch Basin												Can't locate? In the back yard possibly under shed
32334170	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334170		Catch Basin			0-2"				No			inspected_ok		
32334171	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334171		Catch Basin												Witches hat, not inspected
32334176	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334176		Catch Basin			0-2"				No			inspected_ok		
32334177	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334177		Catch Basin			0-2"				No			inspected_ok		
32334178	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334178		Catch Basin			0-2"				No			inspected_ok		
32334184	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334184		Manhole			0-2"				No			inspected_ok		
32334185	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334185		Catch Basin			0-2"				No			inspected_ok		
32334187	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334187		Catch Basin			0-2"				No			inspected_ok		
32334188	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334188		Catch Basin			0-2"				No			inspected_ok		
32334191	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334191		Catch Basin			0-2"				No			inspected_ok		
32334193	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334193		Manhole			4-6				No			inspected_ok		
32334195	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334195		Catch Basin			0-2"				No			inspected_ok		
32334196	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/26/2018	
32334196		Catch Basin			0-2"				No			inspected_ok		
32334220	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334220		Catch Basin			0-2"				No			inspected_ok		
32334225	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334225		Catch Basin			0-2"				No			inspected_ok		
32334228	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334228		Manhole			0-2"				No			inspected_ok		
32334229	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334229		Catch Basin			0-2"				No			inspected_ok		
32334230	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334230		Catch Basin			0-2"				No			inspected_ok		
32334233	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334233		Manhole			0-2"				No			inspected_ok		
32334235	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334235		Manhole			0-2"				No			inspected_ok		
32334236	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32334236		Catch Basin			0-2"				No			inspected_ok		
32334237	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334237		Manhole			0-2"				No			inspected_ok		
32334238	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334238		Catch Basin			0-2"				No			inspected_ok		
32334239	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334239		Manhole			0-2"				No			inspected_ok		
32334240	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334240		Catch Basin			0-2"				No			inspected_ok		
32334241	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334241		Manhole			0-2"				No			inspected_ok		
32334244	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334244		Manhole			0-2"				No			inspected_ok		
32334245	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334245		Manhole			0-2"				No			inspected_ok		
32334246	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334246		Catch Basin			0-2"				No			inspected_ok		
32334247	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334247		Catch Basin			0-2"				No			inspected_ok		
32334248	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334248		Manhole			0-2"				No			inspected_ok		
32334251	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334251		Manhole			0-2"				No			inspected_ok		
32334252	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334252		Manhole			0-2"				No			inspected_ok		
32334253	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334253		Catch Basin			0-2"				No			inspected_ok		
32334254	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334254		Manhole			0-2"				No			inspected_ok		
32334255	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334255		Manhole			0-2"				No			inspected_ok		
32334256	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334256		Catch Basin			0-2"				No			inspected_ok		
32334257	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334257		Catch Basin			0-2"				No			inspected_ok		
32334258	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334258		Manhole			0-2"				No			inspected_ok		
32334312	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334312		Manhole			0-2"				No			inspected_ok		
32334314	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32334314		Catch Basin			0-2"				No			inspected_ok		
32334532	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	This beehive is buried under rocks
32334532		Catch Basin			2-4				No			inspected_ok		
32335001	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335001		Catch Basin			0-2"				No			inspected_ok		
32335004	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335004		Catch Basin			0-2"				No			inspected_ok		
32335007	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335007		Catch Basin			0-2"				No			inspected_ok		
32335012	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335012		Catch Basin			0-2"				No			inspected_ok		
32335014	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335014		Catch Basin			0-2"				No			inspected_ok		
32335015	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335015		Catch Basin			0-2"				No			inspected_ok		
32335019		Manhole			0-2"				No			inspected_ok		
32335020	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32335020		Manhole			0-2"				No			inspected_ok		
32335021	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335021		Catch Basin			0-2"				No			inspected_ok		
32335026	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335026		Manhole										inspected_ok		Under construction witches hat
32335027	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335027		Catch Basin			0-2"				No			inspected_ok		
32335028	401	NA			6"		Good		Yes	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335028		Catch Basin										inspected_ok		Under construction
32335030	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335030		Manhole										inspected_ok		Motor home covering could not check
32335031	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335031		Manhole			0-2"				No			inspected_ok		
32335036	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335036		Catch Basin			0-2"				No			inspected_ok		
32335037	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335037		Catch Basin			0-2"				No			inspected_ok		
32335039	507	NA		12"	None	12	Good		Yes		Arias, Martin	inspected_ok	10/02/2018	No access
32335039		Manhole			0-2"				No			inspected_ok		
32335042	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335042		Manhole			0-2"				No			inspected_ok		
32335044	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335044		Manhole										inspected_ok		Under construction
32335045	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335045		Manhole			0-2"				No			inspected_ok		
32335049	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335049		Manhole			0-2"				No			inspected_ok		
32335050	401	NA			12"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32335050		Catch Basin			0-2"				No			inspected_ok		
32335055	401	NA			12"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32335055		Catch Basin			0-2"				No			inspected_ok		
32335060		Catch Basin			0-2"				No			inspected_ok		
32335061	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335061		Catch Basin			0-2"				No			inspected_ok		
32335062	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335062		Catch Basin			0-2"				No			inspected_ok		
32335064	507	NA			8"		Good		No		Dunaho, Milton	inspected_ok	06/29/2018	
32335064		Manhole			0-2"				No			inspected_ok		
32335073	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335073		Manhole			0-2"				No			inspected_ok		
32335074	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335074		Catch Basin			0-2"				No			inspected_ok		
32335076	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335076		Manhole			0-2"				No			inspected_ok		
32335153	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32335153		Catch Basin			0-2"				No			inspected_ok		
32335154		Manhole			0-2"				No			inspected_ok		
32335163	507	NA		10"	4"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335164	401	NA		7"	3"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335165	401	NA		8"	3"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335166	507	NA		10"	3"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335167	507	NA		10"	5"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335168	401	NA		10"	5"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335169	507	NA		12"	2"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335170	507	NA		12"	3"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335171	401	NA		12"	1"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	
32335172	401	NA		8"	2"		Good		Yes	No	Gorder, Scott	inspected_ok	08/29/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32336001	401	NA			4"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336001		Catch Basin			0-2"				No			inspected_ok		
32336002	507	NA			4"		Good		Yes	No	Bennett, Steve	inspected_ok	07/03/2018	
32336002		Manhole										inspected_ok		Witches hat
32336003	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	07/03/2018	
32336003		Manhole			0-2"				No			inspected_ok		
32336005	401	NA			1"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336005		Catch Basin			0-2"				No			inspected_ok		
32336006	401	NA			2"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336006		Catch Basin			0-2"				No			inspected_ok		
32336008	401	NA			1"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336008		Catch Basin			0-2"				No			inspected_ok		
32336009	401	NA			2"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336009		Catch Basin			6-8			07/20/17	No		62187	clean_complete	07/20/17	
32336010	401	NA			1"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336010		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336011	507	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336011		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336012	507	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336012		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336015	401	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336015		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336016	401	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336016		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336017	507	NA			1"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336017		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336018	507	NA			4"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336018		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336019	401	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336019		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336020	401	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336020		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336021	507	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336021		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336231	401	NA			2"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336231		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336232	507	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336232		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336235	401	NA			None		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336235		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336236	401	NA			2"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336236		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336239	507	NA			8"		Good		No	No	Bennett, Steve	inspected_ok	07/03/2018	
32336239		Manhole			6-8			07/20/17	No			inspected_ok	07/20/17	
32424001	507	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424001		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424003	401	NA			None		Good		Yes	No	Amell, Mark	inspected_ok	06/20/2018	
32424003		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424005	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424005		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424008	507	NA			6"		Good		Yes		Amell, Mark	clean_complete	07/25/2018	
32424008		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424014	507	NA			8"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32424014		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424015	507	NA			6"		Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32424015		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424017	507	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32424017		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424018	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424018		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424019	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424019		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424023	401	NA							No	No	Arias, Martin	clean_complete	10/02/2018	Can not find looks like paved over. Abandoned basin 10/2/18
32424025	507	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424025		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424026	401	NA			6"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32424026		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32424033	507	NA			3"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424033		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32424035	507	Instal: 2016			4"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424035		Manhole	Type 2	20-22"	6-8	18	Good	10/31/17	Yes	No		clean_complete	10/31/17	Instal: 2016
32424036	401	Instal: 2016			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32424036		Catch Basin	Type 1	16-18"	2-4	12	Good	10/31/17	Yes	No		clean_complete	10/31/17	Instal: 2016
32425001	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425001		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425002	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425002		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425008	507	NA			6"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425008		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425009	401	NA			6"		Poor		No	No	Amell, Mark	inspected_ok	08/24/2018	Concrete missing inhaling at grate
32425009		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32425011	507	NA			4"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32425011		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425012	507	NA			4"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32425012		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425016	401	NA			6"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425016		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425020	401	NA			8"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32425020		Catch Basin			6-8			6/20/17	No			inspected_ok	6/20/17	
32425029	507	NA			10"		Good		Yes	No	Dunaho, Milton	inspected_ok	09/19/2018	No access at all, only by foot down hill from back of Carrs building.
32425035	507	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425035		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32425038	507	NA			4"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32425038		Manhole			4-6			6/20/17	No			inspected_ok	6/20/17	
32425039		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425040	401	NA			6"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425040		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32425041	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425041		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425042	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425042		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32425048	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425048		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32425049	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425049		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32425052	401	NA			4"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32425052		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32425054	507	NA			8"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32425054		Manhole			2-4			6/20/17	No			inspected_ok	06/20/17	
32426001	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426001		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426002	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426002		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426004	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32426004		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426007	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426007		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426019	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426019		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426022	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426022		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426026	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32426026		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32426028	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426028		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426032	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426032		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426033	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426033		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426034	507	NA			10"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32426034		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32426039	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426039		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32426040	401	NA			8"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32426040		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32426041	401	NA			8"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32426041		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32426042	507	NA			8"		Good		Yes		Amell, Mark	clean_complete	07/26/2018	
32426042		Manhole			4-6			6/21/17	No			inspected_ok	6/21/17	
32426043	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426043		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426044	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426045	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426054	401	NA			10"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32426054		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32426057	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426058	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426058		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32426063	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426063		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426064	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426064		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426066	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426066		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426067	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426067		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426071	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426071		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426075	401	NA			5"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32426075		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426076	401	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/25/2018	
32426076		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426079	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426079		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426085	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426085		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32426086	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426086		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426089	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426089		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32426091	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32426091		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32426093	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426093		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32426096	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426096		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426098	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426098		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426129	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426129		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32426130	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32426130		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427001	507	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427002	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427003	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427003		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427004	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427004		Manhole		2-4"				6/21/17	No			inspected_ok	6/21/17	
32427005	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427005		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427006	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427006		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427007	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427007		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32427014	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427014		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427017	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427017		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427019	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427019		Manhole			4-6			6/21/17	No			inspected_ok	6/21/17	
32427024	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427024		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427027	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427027		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427028	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427028		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427031	507	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427031		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427032	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427032		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427037	401	NA			4"	12	Good		Yes	No		clean_complete	07/23/2018	
32427037		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427038	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427038		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427043	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427043		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427045	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427045		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427046	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427046		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427047	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427047		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427048	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427048		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427049	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427049		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427050	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427050		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32427051	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427051		Manhole			4-6			6/21/17	No			inspected_ok	6/21/17	
32427053	507	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427053		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32427054	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427054		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427055	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427055		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427057	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427057		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427058	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427058		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427060	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427060		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427062	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427062		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427063	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427063		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427066	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427066		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427067	401	NA							Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427067		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427070	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427070		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427071	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427071		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427073	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427073		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427075	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427075		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427080	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427080		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427087	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427087		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427089	401	NA			14"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/23/2018	
32427089		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427091	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427091		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427094	401	NA			11"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427094		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427100	507	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427100		Manhole			4-6			09/19/17	No			inspected_ok	09/19/17	
32427101	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427101		Catch Basin			2-4			09/19/17	No			inspected_ok	09/19/17	
32427112	401	NA			12"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427112		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427132	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427132		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427134	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427134		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427136	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427136		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427152	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427152		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427153	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427153		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427154	401	NA			5"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/23/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32427154		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427162	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427162		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427163	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427163		Catch Basin			0-2"			09/19/17	No			inspected_ok	09/19/17	
32427164	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427164		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427165	401	NA			14"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427165		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427167	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427167		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427168	401	NA			14"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427168		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427171	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427171		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427172	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427172		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32427174	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427174		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32427175	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427175		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427176	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427176		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427182	507	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427182		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427183	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427183		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427188	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427188		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427190	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427190		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427191	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427191		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32427192	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32427192		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32427193	401	NA			10"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32427193		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32428004	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428004		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428006	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428006		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428007	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428007		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428015	507	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428015		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	sinkhole
32428016	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428016		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428017	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428017		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428038	401	NA			4"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	06/21/2018	
32428038		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428039	401	NA			4"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	06/21/2018	
32428039		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428040	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428040		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428041	401	NA			4"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	06/21/2018	
32428041		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32428042	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428042		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428047	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428047		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428048	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428048		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428049	401	NA			4"				Yes	No	Christ (Jr.), Jeffery	clean_complete	08/24/2018	Broken grate, roll curb
32428049		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428050	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428050		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428051	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428051		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428052	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428052		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428067	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	Moved when they put roundabout in
32428067		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428068	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428070	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428070		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428081	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428081		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428082	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428082		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428083	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428083		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428084	401	NA		12"	1"		Good			No	Knoedler, Shawn	inspected_ok	09/27/2018	inspection done. Good no cleaning needed
32428084		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428085	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428085		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428103	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428103		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428104	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428104		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428105	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428105		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428106	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428106		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428114	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428114		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428115	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428115		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428124	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	
32428124		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428129	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428129		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428131	507	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/26/2018	Not a catch basin. Looks like culvert inspection lid.
32428131		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428137	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428137		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428138	507	NA			12"	12	Good		No	No	Christ (Jr.), Jeffery	clean_complete	07/23/2018	
32428138		Manhole			4-6			6/22/17	No			inspected_ok	6/22/17	
32428145	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428145		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428146	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428146		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428149	401	NA			14"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/23/2018	
32428149		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32428150	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428150		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428151	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428151		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428152	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428152		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428153	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428153		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428155	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428156	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428157	507	NA			2"		Good		Yes	No	Dunaho, Milton	inspected_ok	09/19/2018	No access, behind houses with no access for truck. Ends are fenced in
32428158	507	NA							No	No	Dunaho, Milton	inspected_ok	09/19/2018	Either buried under ground or non existent
32428159	507	NA		None	4"				Yes	No	Dunaho, Milton	inspected_ok	09/19/2018	No access, behind houses with no access for truck. Ends are fenced in
32428160	401	NA			3"				Yes	No	Dunaho, Milton	inspected_ok	09/19/2018	No access, behind houses with no access for truck. Ends are fenced in
32428160		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428492	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428493	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428493		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428494	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428494		Catch Basin			4-6			6/22/17	No		62187	clean_complete	07/20/17	
32428495	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428495		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428496	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428496		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428497	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428497		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428498	401	NA			16"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428498		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428499	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428499		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32428500	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428500		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428501	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428501		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428503	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428503		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428507	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32428507		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32428508	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428508		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32428509	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32428509		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32429013	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/21/2018	
32430001	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430001		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430006	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32430006		Catch Basin			6-8			6/22/17	Yes	Yes		clean	6/22/17	Witches hat
32430007	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430007		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430009	507	NA			6"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/22/2018	
32430009		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430011	507	NA			6"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/22/2018	
32430011		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430015	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32430015		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430019	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430019		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32430022	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430022		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430024	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430024		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430026	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430026		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430028	401	NA			8"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32430028		Catch Basin			6-8			6/22/17	Yes		62187	clean_complete	07/21/17	
32430033	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32430033		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430035	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430035		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430038	507	NA			12"	12	Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/09/2018	
32430038		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32430039	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32430039		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32430041	507	NA		18"	4"	12	Good			No	Amell, Mark	clean_complete	10/18/2018	
32430041		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32431001	401	NA			18"	12	Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32431001		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32431009	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32431009		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431011	401	NA			10"	12	Good		Yes		Bennett, Roy	clean_complete	06/19/2018	
32431012	507	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32431012		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431015	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431015		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431016	401	NA			8"	12	Good		Yes		Christ (Jr.), Jeffery	clean_complete	06/22/2018	
32431016		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32431017	401	NA			6"	12	Good		Yes	No	Van Fleet, Myhi	clean_complete	07/09/2018	
32431017		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431018	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32431018		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431019	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431019		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431020	401	NA			8"	12	Good		Yes		Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32431020		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32431021	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431021		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431025	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431025		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431026	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431026		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431027	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431027		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431028	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32431028		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32431042	401	NA			4"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/09/2018	
32431042		Catch Basin						6/22/17	No			inspected_ok	6/22/17	Witch's Hat
32431045	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432001	401	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432001		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432003	401	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432003		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432004	401	NA			2"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432004		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432005	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32432005		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432007	401	NA			2"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432007		Catch Basin			2-4			6/22/17	Yes		62187	clean_complete	07/21/17	
32432010	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432010		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432012	401	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432012		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432013	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432013		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432015	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432015		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432017	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432017		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432018	401	NA			3"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432018		Catch Basin			0-2"			6/22/17	Yes			inspected_ok	6/22/17	
32432019	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432019		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432020	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432020		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432021	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432021		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432022	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432022		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432023	507	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432023		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32432025	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432027	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432027		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32432042	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432045	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432045		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432047	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32432047		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432048	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432048		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432049	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432053	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432053		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432054	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432054		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432055	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432055		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432057	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432057		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32432059	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432059		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32432060	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432075	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432076	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432077	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32432078	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/22/2018	
32433001	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433002	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433007	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433013	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433014	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433014		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32433015	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433015		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433017	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433017		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433018	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433018		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433023	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433023		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433026	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433028	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433028		Catch Basin	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32433029	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433029		Catch Basin	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32433031	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433033	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433033		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32433034	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433034		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32433045		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433049	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433072	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433072		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433073	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433073		Catch Basin			0-2"			6/22/17	Yes			inspected_ok	6/22/17	
32433074	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433074		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433075	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433075		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433076	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433076		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433077	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433077		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433078	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433078		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433079	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433079		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433083	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433083		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433084	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433084		Catch Basin			4-6			6/22/17	Yes		62187	clean_complete	07/21/17	
32433085	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433085		Catch Basin	Type 2	6-8"	0-2"	12	Good	6/22/17	No			inspected_ok	6/22/17	
32433092	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433092		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433098	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433098		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433099	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433099		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433104	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433104		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433105	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433105		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433107	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433107		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433108	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433108		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433109	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32433109		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433110	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433110		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433111	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433111		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433112	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433112		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433113	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433113		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433114	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433114		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433115	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433115		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433124	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433125	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433126	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433128	507	NA			8"	12	Good		Yes	No	Banie, Harold	clean_complete	07/25/2018	
32433133	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433133		Manhole												
32433134	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433134		Catch Basin												
32433135	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433135		Catch Basin	Type 2	8-10"	6-8	12	Good	09/19/17			24417	clean_complete	09/19/17	
32433136	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433136		Catch Basin	Type 2	6-8"	0-2"	12	Good	6/22/17	No			inspected_ok	6/22/17	
32433137	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433137		Catch Basin	Type 2	6-8"	0-2"	12	Good	6/22/17	No			inspected_ok	6/22/17	
32433140	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433140		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433141	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433141		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433144	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433144		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433145	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433145		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433148	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433148		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433149	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433149		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433150	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433150		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433151	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433151		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433162		Manhole			4-6			6/22/17	No			inspected_ok	6/22/17	
32433165	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433165		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433176	401	18			10"	12	Good		Yes	No	Contractor	clean_complete	05/14/2018	
32433176		Catch Basin	Type 1	8-10"	6-8	12		09/19/17				clean	09/19/17	
32433189	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433189		Manhole			4-6			6/22/17	No			inspected_ok	6/22/17	
32433190	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433190		Manhole			4-6			6/22/17	No			inspected_ok	6/22/17	
32433203	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433203		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32433204	507	NA			5"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433204		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32433206	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32433207	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433215	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433217	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433219	507	NA			7"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433232	401	NA			5"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32433232		Catch Basin	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32433235	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433238	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433238		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433239	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32433239		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32433246	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32433255	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	07/27/2018	
32434001	401	NA		15"	12"	12	Good				Christ (Jr.), Jeffery	clean_complete	09/27/2018	
32434008	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32434008		Manhole	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32434009	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32434009		Manhole	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32434010	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/26/2018	
32434011	507	NA			7"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/27/2018	Asphalt needs to be cut Over the lid
32434021	507	NA			6"	12	Good		Yes	No	Banie, Harold	clean_complete	07/25/2018	
32434021		Manhole	Type 1	8-10"	4-6	12		6/22/17	Yes			clean	6/22/17	
32434026	401	NA		8"	2"	12	Good				Christ (Jr.), Jeffery	clean_complete	09/27/2018	
32434027	401	NA			7"	12	Good		Yes	No	Banie, Harold	clean_complete	07/25/2018	
32434027		Catch Basin	Type 1	8-10"	4-6	12		6/22/17	Yes			clean	6/22/17	
32434042	401	NA			4"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32434042		Catch Basin	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32525001	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525001		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525002	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525002		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525003	507	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	
32525003		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525014	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525014		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525036		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32525039		Catch Basin			8-10			6/20/17	No			inspected_ok	6/20/17	
32525040	507	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525040		Manhole			8-10			6/20/17	No			inspected_ok	6/20/17	
32525041	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525041		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32525043	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525043		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525044	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525044		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32525046	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525046		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32525055	507	NA			7"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525055		Manhole			6-8			6/20/17	No			inspected_ok	6/20/17	
32525064	507	NA			10"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525064		Manhole						6/20/17	No			inspected_ok	6/20/17	Witches hat on top of basin.
32525065	401	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32525065		Catch Basin						6/20/17	No			inspected_ok	6/20/17	Witches hat on top of basin.
32526001	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526001		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526002	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526002		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32526003	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526003		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526006	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526006		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526008	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526008		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526009	401	NA			1"		Good		No		Dunaho, Milton	inspected_ok	08/29/2018	
32526009		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32526010	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526010		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526012	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526012		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526013	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526013		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526014	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526014		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526015	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526015		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526020	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526020		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526021	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526021		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526041		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	Solid lid and 10 feet into the yard.
32526048	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526048		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526049	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526049		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526052	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526052		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526064		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	Solid lid and 4 feet into the yard.
32526070		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	Solid lid and 8 feet in the yard.
32526079	401	NA							No		Bennett, Roy	inspected_ok	06/21/2018	
32526079		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32526080	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526080		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32526084	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526084		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32526085	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526085		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526086	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526086		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526087	401	NA			6"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32526091	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526091		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526092	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526092		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526093	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526093		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526099	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526099		Manhole			6-8			6/20/17	No			inspected_ok	6/20/17	
32526139	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526139		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526140	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32526140		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526141	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526141		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526142	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32526142		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526144	401	NA			8"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32526144		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526145	401	NA			10"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32526145		Catch Basin			6-8			6/20/17	No			inspected_ok	6/20/17	
32526146	401	NA			4"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32526146		Catch Basin			2-4			6/20/17	No			inspected_ok	6/20/17	
32526147	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526147		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526149	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526149		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526151	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526151		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526152	401	NA			6"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32526152		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526227	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526227		Manhole			2-4			6/20/17	No			inspected_ok	6/20/17	
32526230	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526230		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526231	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526231		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526232	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526232		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526233	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526233		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526236	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526236		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32526237	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32526237		Catch Basin			4-6			6/20/17	No			inspected_ok	6/20/17	
32527006	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527006		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527014	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527014		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527017	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527017		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527021	401	NA			3"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32527021		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527029	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527029		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527036	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527036		Manhole			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527083	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527083		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527092	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527092		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527093	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527093		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527094	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527094		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527098	401	NA			4"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32527098		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527099	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527099		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527100	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527100		Catch Basin			0-2"			6/20/17	No			inspected_ok	6/20/17	
32527107		Manhole						6/21/17	No			inspected_ok	6/21/17	Buried under sod. Not cleanable.
32527113	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32527113		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527114	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527114		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527115	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527115		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527117	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527117		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527118	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527118		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527119	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527119		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527121	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527121		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527122	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527122		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527123	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527123		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527128	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527128		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527129	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527129		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527131	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527131		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527134	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527134		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527137	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527137		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527141	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527141		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527145	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527145		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527146	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527146		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527155	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527155		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527156	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527156		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527157	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527157		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527161	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	Needs new great
32527161		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	Broken roll curb lid.
32527162	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527162		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527163	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527163		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527182	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527182		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527183	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527183		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527187	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527187		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527189	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527189		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527191	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527191		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527197	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527197		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32527199	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527199		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527200	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527200		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527208	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527208		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527209	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527209		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527212	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527212		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527213	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527213		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527218	401	NA			4"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32527218		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527219	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527219		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527220	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527220		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527221	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527221		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527222	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527222		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527224	401	NA			4"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32527224		Catch Basin			4-6			6/21/17	No			inspected_ok	6/21/17	
32527225	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527225		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527226	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527226		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527230	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527230		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527232	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527232		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527234	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527234		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527237	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527237		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527242	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527242		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527243	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527243		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527247	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527247		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527250	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527250		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527252	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527252		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527253	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527253		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527262	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527262		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527266	401	NA			2"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32527266		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527267	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527267		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527268	401	NA			6"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	
32527268		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527269	401	NA			4"		Good		Yes	No	Bennett, Roy	clean_complete	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32527269		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527271	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527271		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527274	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527274		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527275	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527275		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527279	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527279		Manhole			4-6			6/21/17	No			inspected_ok	6/21/17	
32527280	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527280		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527281	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527281		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527282	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32527282		Manhole			2-4			6/21/17	No			inspected_ok	6/21/17	
32527293	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527293		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527296	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527296		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527297	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527297		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527298	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527298		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32527302	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527302		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	Slotted lid. 4 feet into park strip.
32527303	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527303		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527304	401	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527304		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527307	507	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527307		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527310	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527310		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527314	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527314		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527315	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527315		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527316	507	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527316		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527319	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527319		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527320	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527320		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527321	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527321		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527322		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527323	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527323		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527325	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527325		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527327	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527327		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527328	401	NA			6"		Good		Yes		Bennett, Roy	clean_complete	08/24/2018	
32527328		Catch Basin			6-8			6/21/17	No			inspected_ok	6/21/17	
32527332	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527332		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527333	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32527333		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527335	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527335		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527337	507	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527337		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527338	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527338		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527340	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527340		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527343	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527343		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527472	401	NA			6"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32527472		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527473	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527473		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527474	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527474		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527617	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527617		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527625	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32527625		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32527646	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32527646		Catch Basin						6/21/17	No			inspected_ok	6/21/17	
32528008	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528008		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528009	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528009		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528015	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528015		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528016	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528016		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528017	507	NA			4"				No		Dunaho, Milton	inspected_ok	06/15/2018	
32528017		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528021		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528022	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528022		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528044	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528044		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528045	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528045		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32528047	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528047		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528048	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528048		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528056	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528056		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528065	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528065		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528066	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528066		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528069	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528069		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528073	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528073		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528074	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528074		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528075	401	NA			2"				No		Bennett, Roy	inspected_ok	06/21/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32528075		Catch Basin			0-2"			6/21/17				inspected_ok	6/21/17	
32528077	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528077		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528078	507	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528078		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528079	507	NA			None		Good				Dunaho, Milton	inspected_ok	08/29/2018	
32528080	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528080		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528086	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528086		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528087	401	NA			6"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32528087		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32528088	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528088		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528089	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528089		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528090	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528090		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528091	507	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528091		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528092	401	NA			4"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528092		Catch Basin			2-4			6/21/17	No			inspected_ok	6/21/17	
32528093	401	NA			1"				No		Bennett, Roy	inspected_ok	06/21/2018	
32528093		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528106	401	NA			None				No		Bennett, Roy	inspected_ok	06/21/2018	
32528106		Catch Basin			0-2"			6/21/17	No			inspected_ok	6/21/17	
32528107		Manhole			0-2"			6/21/17	No			inspected_ok	6/21/17	Sold lid in median
32529001	507	NA			3"				No		Bennett, Roy	inspected_ok	06/21/2018	
32529001		Manhole						6/21/17	No			inspected_ok	6/21/17	Under construction witches hat
32530005	401	NA			1"				Yes	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530005		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530007	401	NA			3"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530007		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32530008	401	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530008		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530011		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530012	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530012		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530014	401	NA			4"				No	No	Bennett, Steve	inspected_ok	06/22/2018	
32530014		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32530015	507	NA							No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530015		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530018	507	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530018		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32530019	507	NA			None				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530019		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530020	507	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	Face is broken out of drain.
32530020		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530021	507	NA			None				Yes	No	Van Fleet, Myhi	inspected_ok	06/22/2018	Face of drain broken
32530021		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530025	507	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530025		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530027	401	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530027		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530028	401	NA			1"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530028		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32530029	401	NA			6"	12	Good		Yes	No	Van Fleet, Myhi	clean_complete	07/09/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32530029		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32530030	401	NA			4"	12	Good		No	No	Amell, Mark	clean_complete	10/18/2018	
32530030		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32530031	401	NA			4"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32530031		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531006	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531006		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531007	507	NA			8"	12	Good		Yes		Bennett, Roy	clean_complete	07/09/2018	
32531007		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32531008	507	NA			6"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531008		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531010	507	NA			2"				No	No	Van Fleet, Myhi	inspected_ok	06/22/2018	
32531010		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531012	401	NA			5"		Good		Yes	No	Bennett, Roy	clean_complete	07/09/2018	
32531014	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531014		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531015	401	NA			12"	12	Good		Yes		Bennett, Roy	clean_complete	07/09/2018	
32531015		Catch Basin			8-10			6/22/17	Yes		62187	clean_complete	07/21/17	
32531016	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531016		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531019	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531019		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531021	401	NA			6"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531021		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531028	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531028		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531029	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531029		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531030	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531030		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32531031	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531031		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32531033	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531033		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32531036	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32531036		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532003	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532003		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532008	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532008		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532009	401	NA			4"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32532009		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32532010	507	NA			4"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32532010		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532013	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532013		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532014	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532014		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532015	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532015		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532016	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532016		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532017	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532017		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532018	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532018		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532019	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32532019		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532022	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532022		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532023	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532023		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532024	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532024		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532026	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532026		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532027	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532027		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532029	401	NA			8"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32532029		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532030	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532030		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	road curb lid broken
32532031	507	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532031		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532035	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532035		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532036	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532036		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532038	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532038		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532039	401	NA			6"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532039		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532042	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532042		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532043	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532043		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532044	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532044		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532045	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532045		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532046	507	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532046		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532048	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532048		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532051	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532051		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532062	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532062		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532064	507	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532064		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532084	507	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532084		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532091	507	NA			10"		Good				Christ (Jr.), Jeffery	clean_complete	09/19/2018	
32532091		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532094	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32532094		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532097		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532098	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532098		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	Broke curb lid
32532100	401	NA			6"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32532100		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532110	507	NA			10"		Poor		No		Christ (Jr.), Jeffery	clean_complete	06/20/2018	Grate missing teeth. Needs replaced
32532110		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532132	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32532132		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32532134	507	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32532134		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533001	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533001		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533002	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533002		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533009	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533009		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533013	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533013		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533022	401	NA			2"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533022		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533029	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533029		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533030	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533030		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533033	401	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533033		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32533036	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533036		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533038	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533038		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533039	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533039		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533060	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533060		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533061	507	NA		12"	6"	12	Good		Yes		Dunaho, Milton	inspected_ok	10/04/2018	No access to clean 9/27/18
32533061		Manhole			6-8			6/22/17	Yes	Yes		clean	6/22/17	
32533067	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533067		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533068	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533068		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533078	401	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533078		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32533079	401	NA			10"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533079		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32533081	401	NA			10"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533081		Catch Basin			2-4			6/22/17	No			inspected_ok	6/22/17	
32533083	401	NA			7"		Good		Yes	No	Lyman, Brian	clean_complete	08/27/2018	
32533083		Catch Basin			6-8			6/22/17	Yes			clean	6/22/17	
32533084	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533084		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533086	401	NA			4"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32533086		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533087	401	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533087		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533092	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533092		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533093	401	NA			3"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533093		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533094	401	NA			4"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533094		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533096	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533096		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533097	507	NA			10"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533097		Manhole			4-6			6/22/17	No			inspected_ok	6/22/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32533098	401	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533098		Catch Basin			4-6			6/22/17	No			inspected_ok	6/22/17	
32533103	507	NA			7"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533103		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533104	401	NA			7"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533104		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533105	507	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533105		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533109	507	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533109		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533114	401	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533114		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533115	401	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	
32533115		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533120	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533120		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533121	401	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	
32533121		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533122	401	NA			1"				No		Bennett, Steve	clean_complete	08/30/2018	
32533122		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533137	507	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533137		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533139	507	NA			6"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533139		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533143	507	NA			4"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533143		Manhole			2-4			6/22/17	No			inspected_ok	6/22/17	
32533144	401	NA			4"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533144		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533145	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533145		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533149	507	NA			4"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533149		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533155	401	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533155		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533156	401	NA			3"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533156		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533159	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533159		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533160	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533160		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533167	507	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	No access to clean
32533167		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533171	401	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	
32533171		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533172	401	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533172		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533174	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533174		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533176	401	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	
32533176		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533181	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533181		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533186	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32533186		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533190	507	NA			2"				No		Bennett, Roy	inspected_ok	06/20/2018	No access
32533190		Manhole			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533198	401	NA			None				No		Bennett, Roy	inspected_ok	06/20/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32533198		Catch Basin			0-2"			6/22/17	No			inspected_ok	6/22/17	
32533209	507	NA			10"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533209		Manhole						6/22/17	No			inspected_ok	6/22/17	
32533210	401	NA			10"				Yes		Bennett, Steve	clean_complete	08/30/2018	
32533210		Catch Basin						6/22/17	No			inspected_ok	6/22/17	
32533213		Catch Basin						6/22/17	No			inspected_ok	6/22/17	
32534010	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32534010		Catch Basin	Type 1	8-10"	0-2"	12		6/22/17	No			inspected_ok	6/22/17	
32534011		Catch Basin	Type 1	8-10"	4-6	12		6/22/17	Yes			clean	6/22/17	
32534013	401	NA			7"				Yes	No	Bennett, Roy	inspected_ok	10/19/2018	No access MOA 9/27/18
32534013		Catch Basin	Type 1	8-10"	4-6	12		6/22/17	Yes			clean	6/22/17	
32535005	401	NA			1"	12	Good		Yes	No	Dunaho, Milton	inspected_ok	08/30/2018	
32536004	401	NA			1"		Good		Yes	No	Dunaho, Milton	inspected_ok	08/30/2018	
32537001	507	NA			1"	12			Yes	No	Dunaho, Milton	inspected_ok	08/30/2018	
32537002	507	NA			1"	12	Good		Yes	No	Dunaho, Milton	inspected_ok	08/30/2018	
32626001	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626001		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626002	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626002		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626005	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626005		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626006	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626006		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626007	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626007		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626031	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626031		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626034	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626034		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626035	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626035		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626036	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626036		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626037	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626037		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626048	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626048		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626049	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626049		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626051	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626051		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626055	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626055		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626056	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626056		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626065	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626065		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626068	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626068		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626069	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626069		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626071	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626071		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626072	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626072		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626085	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626085		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32626086	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626086		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626095	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626095		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626096	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626096		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626105	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626105		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626106	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626106		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626107	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626107		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32626108	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32626108		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627006	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627006		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627007	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627007		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627014	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627014		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627016	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627016		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627024	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627024		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627026	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627026		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627027	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627027		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627029	401	NA			8"		Good		Yes	No	Dunaho, Milton	clean_complete	08/24/2018	
32627029		Catch Basin			4-6			6/27/17	No			inspected_ok	6/27/17	
32627030	401	NA			6"		Good		Yes	No	Dunaho, Milton	clean_complete	08/24/2018	
32627030		Catch Basin			4-6			6/27/17	No			inspected_ok	6/27/17	
32627032	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627032		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627037	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627037		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627039	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627039		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627042	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627042		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627043	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627043		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627048	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627048		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627052	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627052		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627057	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627057		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627059	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627059		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627060	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627060		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627066	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627066		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627067	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627067		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627068	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32627068		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627073	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627073		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627074	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627074		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627078	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627078		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627087	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627087		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627090	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627090		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627091	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627091		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627092	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627092		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627093	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627093		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627098	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627098		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627099	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627099		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627100	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627100		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627101	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627101		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627106	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627106		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627107	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627107		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627109	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627109		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627110	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627110		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32627120	401	NA			8"	12	Good		Yes	No	Banie, Harold	clean_complete	07/23/2018	
32627120		Catch Basin			2-4			6/27/17	No			inspected_ok	6/27/17	
32627143	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627143		Manhole			6-8			6/27/17	Yes		62187	clean_complete	07/21/17	
32627147	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32627147		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628001	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628001		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628002	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628002		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628015	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628015		Catch Basin			8-10			6/27/17	No			inspected_ok	6/27/17	
32628016	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628016		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628017	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628017		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628020	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628020		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628021	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628021		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628024	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628024		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628025	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628025		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32628031	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628031		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628032	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628032		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628038	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628038		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628039	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628039		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	Broken drain face
32628040	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628040		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628041	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628041		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628042	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628042		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32628045	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32628045		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629005	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32629005		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629008	401	NA			8"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32629008		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629009	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32629009		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629010	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32629010		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629017	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32629017		Manhole			0-2"			6/27/17	No			inspected_ok	6/27/17	
32629018	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32629018		Catch Basin			0-2"			6/27/17	No			inspected_ok	6/27/17	
32630005	401	NA			12"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	
32630005		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630006	401	NA			12"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	
32630006		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630008	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630008		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630009	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630009		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630012	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630012		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630013	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630013		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630014	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630014		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630020	401	NA			4"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32630020		Catch Basin			4-6			6/28/17	Yes		62187	clean_complete	07/21/17	
32630021	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630021		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630025	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630025		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630026	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630026		Catch Basin			6-8			6/28/17	Yes		62187	clean_complete	07/21/17	
32630028	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630028		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630029	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630029		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32630032	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630032		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630033	507	NA			4"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32630033		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630034	401	NA			4"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32630034		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630039	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630039		Catch Basin						6/28/17	No			inspected_ok	6/28/17	
32630040	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630040		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630041	401	NA			6"	12	Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	07/10/2018	
32630041		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32630042	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630042		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630043	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630043		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630044	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630044		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630045	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630045		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630048	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630048		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630065	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630065		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630066	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630066		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630068	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630068		Catch Basin			6-8			6/28/17	Yes		62187	clean_complete	07/21/17	
32630070	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630070		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630071	401	NA			4"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32630071		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630072	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630072		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630073	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32630073		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32630080	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32630080		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32631001	507	NA			4"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	
32631001		Manhole			2-4			6/28/17	No			inspected_ok	6/28/17	
32631002	401	NA			6"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	
32631002		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32632001	401	NA			None		Good			No	Lyman, Brian	inspected_ok	08/28/2018	
32632001		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632002	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632002		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632003	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632003		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632004	401	NA			6"	12	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	Removed then reinstalled witches hat.
32632007	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632007		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632008	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632008		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632012	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632012		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632015	401	NA			None		Good			No	Lyman, Brian	inspected_ok	08/28/2018	
32632015		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632017	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632017		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632044	401	NA			6"	15	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32632044		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32632045	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632045		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632047	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	Broken grate needs replaced
32632047		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632048	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632048		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632051	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632051		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632052	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632052		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632053	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632053		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632057	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632057		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632059	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632059		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632060	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632060		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632066		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632086	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32632086		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32632089	401	NA			6"	12	Good		Yes	No	Lyman, Brian	clean_complete	06/19/2018	
32632089		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633001	401	NA		12"	6"	18	Good		Yes	No	Amell, Mark	clean_complete	10/05/2018	and cleaned, construction done
32633001		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32633002	401	NA			6"	12	Good		Yes		Beesley, Earle	clean_complete	07/25/2018	
32633002		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32633006	401	NA			4"	12	Good		Yes	No	Banie, Harold	clean_complete	07/25/2018	
32633006		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633007	401	NA			6"	24	Good		Yes		Bell, Brian, Brian	clean_complete	07/26/2018	
32633007		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32633010	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633010		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633011	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633011		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633012	401	NA			6"				Yes		Bennett, Steve	clean_complete	08/29/2018	
32633012		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32633013	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633013		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633014	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633014		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32633015	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633015		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633016	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633016		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633018	401	NA		12"	1"	24	Good		Yes	No	Amell, Mark	clean_complete	10/05/2018	and cleaned
32633035	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633035		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32633072	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32633072		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634005	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634005		Catch Basin			4-6			6/28/17	Yes			clean	6/28/17	East of trail
32634006	401	NA			6"	12	Good		Yes	No	Banie, Harold	clean_complete	07/24/2018	
32634006		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32634007	401	NA			12"	12	Good		Yes		Bell, Brian, Brian	clean_complete	06/19/2018	
32634007		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32634008	401	NA		12"	1"	18	Good			No	Amell, Mark	clean_complete	10/05/2018	and cleaned, construction done
32634009	401	NA		12"	4"	18	Good			No	Amell, Mark	clean_complete	10/05/2018	and cleaned, construction done
32634011	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634011		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634012	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634012		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32634013	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634013		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634014	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634014		Manhole			4-6			6/28/17	Yes			clean	6/28/17	
32634015	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634015		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634018	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634018		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634020	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634020		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634021	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634021		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634023	507	NA			Greater than 24"	12	Good		Yes		Bell, Brian, Brian	clean_complete	07/26/2018	
32634023		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634027	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634027		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634028	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634028		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634029	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634029		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634031	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634031		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634032	401	NA			8"				Yes		Christ (Jr.), Jeffery	clean_complete	08/10/2018	
32634046	401	NA			4"				Yes	No	Christ (Jr.), Jeffery	clean_complete	08/10/2018	Needs new lid, this ones the wrong size and sticks up. Will be bad for plowing
32634046		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634047	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634047		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634048	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634048		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634052	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634052		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634059	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634059		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634126	401	NA			4"				Yes		Christ (Jr.), Jeffery	clean_complete	08/10/2018	
32634126		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634191	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634191		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634205	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634205		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634226	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634226		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634227	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634227		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634233	401	NA		20"	18"	15	Good			No	Mathis, Linus	clean_complete	10/04/2018	
32634240	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634240		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32634242	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32634242		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634244	401	NA		12"	6"	12	Good				Dunaho, Milton	inspected_ok	10/04/2018	Witches hat, still under construction MOA 9/27/18
32634244		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634246	401	NA		12"	3"	12	Good				Dunaho, Milton	inspected_ok	10/04/2018	Witches hat, still under construction MOA 9/27/18

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32634251	401	NA			6"				Yes		Christ (Jr.), Jeffery	clean_complete	08/10/2018	
32634251		Catch Basin			2-4			6/28/17	No			inspected_ok	6/28/17	
32634252	401	NA		18"	24"	12	Good			No	Mathis, Linus	clean_complete	10/04/2018	Witches hat, still under construction MOA 9/27/18
32634254	401	NA			7"				Yes		Christ (Jr.), Jeffery	clean_complete	08/10/2018	
32634254		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32634257	507	NA		Greater than 24"	Greater than 24"	42	Good		No	No	Mathis, Linus	clean_complete	10/04/2018	
32635001	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32635001		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32635003	401	stalled by StMaint 2000			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32635003		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	Installed by StMaint 2000
32635004	507	stalled by StMaint 2000			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32635004		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	Installed by StMaint 2000
32635005	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32635005		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32635083	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/19/2018	
32635083		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636001	507	2009 MOASTMNT			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636001		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	2009 MOASTMNT
32636003	507	2009 MOASTMNT			3"		Good		Yes		Bennett, Steve	clean_complete	08/29/2018	
32636003		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	2009 MOASTMNT
32636030	507	NA			6"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636030		Manhole						6/28/17	No			inspected_ok	6/28/17	
32636031	507	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636031		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636032	507	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636032		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636034	401	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636034		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636035	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636035		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636037	401	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636037		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636038	401	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636038		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636040	401	NA			4"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636040		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636042	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636042		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636043	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636043		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636045	507	NA							No	No	Amell, Mark	inspected_ok	06/20/2018	Not a catch basin
32636045		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636046	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636046		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636047	507	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636047		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636048	401	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636048		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636050	507	NA			2"		Good		No	No	Van Fleet, Myhi	inspected_ok	06/20/2018	
32636050		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636051	401	NA			2"		Good		No	No	Van Fleet, Myhi	inspected_ok	06/20/2018	
32636051		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636052	507	NA			1"		Good		No	No	Van Fleet, Myhi	inspected_ok	06/20/2018	
32636052		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636122	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636122		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636123	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32636123		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636124	401	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636124		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636125	507	NA			1"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636125		Manhole			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636126	401	NA			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32636126		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32636132	401	NA			8"		Good		Yes		Bennett, Steve	clean_complete	08/29/2018	
32636132		Catch Basin			0-2"			6/28/17	No			inspected_ok	6/28/17	
32637001	401	NA			2"		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32637001		Catch Basin			4-6			6/28/17	No			inspected_ok	6/28/17	
32727014	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727014		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727020	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727020		Manhole						6/29/17	No			inspected_ok	6/29/17	
32727028	507	NA							No		Bennett, Roy	inspected_ok	06/15/2018	
32727028		Manhole						6/29/17	No			inspected_ok	6/29/17	River flowing through
32727034	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727034		Catch Basin						6/29/17	No			inspected_ok	6/29/17	Rotted pipe
32727036	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727036		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727037	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727037		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727042	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	Needs new great
32727042		Catch Basin						6/29/17	No			inspected_ok	6/29/17	10" outfall
32727043	401	NA							No		Bennett, Roy	inspected_ok	06/15/2018	
32727043		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727045	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727045		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727052	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727052		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	Structure is corroding around pipe. 10" outfall
32727054	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727054		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	Structure Corroding around pipe. 10" outfall
32727060	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727060		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32727071	401	NA			5"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727071		Catch Basin	Type 1					6/29/17	No			inspected_ok	6/29/17	
32727072	507	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727072		Manhole						6/29/17	No			inspected_ok	6/29/17	Rotted pipe in basin
32727073	401	NA			5"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727073		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727075	507	NA							No		Bennett, Roy	inspected_ok	06/15/2018	
32727075		Manhole						6/29/17	No			inspected_ok	6/29/17	
32727076		Catch Basin						6/29/17	No			inspected_ok	6/29/17	Cracked lid
32727081		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727082	507	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727082		Manhole						6/29/17	No			inspected_ok	6/29/17	
32727093	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32727093		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32727094	401	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32727094		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728002	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728002		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728003	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728003		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728005	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728005		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32728008	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728008		Catch Basin				10		6/29/17	Yes			clean_complete	6/29/17	
32728012	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728012		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728014	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728014		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728017	507	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728017		Manhole						6/29/17	No			inspected_ok	6/29/17	
32728023	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728023		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728034	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728034		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728035	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728035		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728040	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728040		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728041	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728041		Catch Basin	Type 1			10		6/29/17	No			inspected_ok	6/29/17	
32728047		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728048	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728048		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728050	401	NA			2"				Yes		Bennett, Roy	clean_complete	08/24/2018	
32728050		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728051	401	NA			1"				Yes		Bennett, Roy	clean_complete	08/24/2018	
32728051		Catch Basin		0		10		6/29/17	No			inspected_ok	6/29/17	
32728052		Catch Basin		0				6/29/17	No			inspected_ok	6/29/17	0" sump
32728053		Catch Basin						6/29/17	No			inspected_ok	6/29/17	0" sump
32728057	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728057		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728058	401	NA			2"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32728058		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728059	401	NA			2"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32728059		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728066	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728066		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728084	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728084		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728085	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728085		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728087	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728087		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728088	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728088		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728090	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728090		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728091	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728091		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728092	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728092		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728097	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728097		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728098	401	NA			6"				Yes		Bennett, Steve	clean_complete	08/29/2018	
32728098		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728100	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728100		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728102	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728102		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32728107	507	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728107		Manhole						6/29/17	Yes			clean	6/29/17	Needs flexible hose and reducer to clean.
32728109	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728109		Manhole						6/29/17	No			inspected_ok	6/29/17	
32728111	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728111		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728118	401	NA			3"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32728118		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728125	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	Needs a new great roll curb
32728125		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32728131	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728131		Catch Basin				10	Poor	6/29/17	No			inspected_ok	6/29/17	Rotted pipe
32728134	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728134		Catch Basin				10		6/29/17	Yes			clean_complete	6/29/17	
32728135	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728135		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728136	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32728136		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32728141	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32728141		Catch Basin				10		6/29/17	No			inspected_ok	6/29/17	
32729002	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729002		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729003	507	NA			4"				Yes		Butler, Ron	clean_complete	08/29/2018	
32729003		Manhole			6-8			6/29/17	No			inspected_ok	6/29/17	
32729009	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729009		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32729010	401	NA			2"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32729010		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32729012		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32729013	507	NA			8"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/24/2018	
32729013		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729016	401	NA			6"				No		Bennett, Roy	inspected_ok	06/19/2018	
32729016		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32729018	401	NA			3"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729028	401	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729028		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729029	507	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729029		Manhole			8-10			6/29/17	Yes		20270	clean_complete	07/26/17	Face of grate broken
32729030	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729030		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729031	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729031		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729035		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32729039	401	NA			2"	12	Good		Yes	No	Bennett, Roy	clean_complete	07/23/2018	
32729039		Catch Basin						6/29/17	No			inspected_ok	6/29/17	
32729045	401	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729045		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729048	401	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729048		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729050	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729050		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729052	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729052		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729054	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32729054		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729057	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32729057		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729058	507	NA			1"				Yes		Bennett, Roy	inspected_ok	06/15/2018	
32729058		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32729063	401	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729063		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32729065	507	NA			None				No		Bennett, Roy	inspected_ok	06/15/2018	
32729065		Catchbasin Manhole						6/29/17	No			inspected_ok	6/29/17	
32730015	507	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730015		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730025	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730025		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730029	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730031	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730035	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730038	507	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730038		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730040	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730040		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730041	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730041		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730045	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730045		Catch Basin			6-8			6/29/17	Yes		20270	clean_complete	07/26/17	
32730046	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730046		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730047	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730047		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730048	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730048		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730051	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730051		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730056	401	NA			5"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730056		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730062	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730062		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730064	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730064		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32730065	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730065		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730066	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730066		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730071	401	NA			4"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32730071		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730074	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730074		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730086	401	NA							Yes		Bennett, Steve	inspected_ok	08/29/2018	Top intake for a pipe, but not a catch basin.
32730086		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730089	507	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730089		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730091	507	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730091		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	Broken lid
32730092	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730092		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730093	401	NA			3"				No		Bennett, Roy	inspected_ok	06/15/2018	
32730093		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730094	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32730094		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730095	401	NA			2"				No		Bennett, Roy	inspected_ok	06/15/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32730095		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730096	401	NA			1"				No		Bennett, Roy	inspected_ok	06/15/2018	
32730096		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730097	401	NA			6"				Yes		Bennett, Steve	clean_complete	08/29/2018	
32730097		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730098	401	NA			4"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32730098		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730099	401	NA			12"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32730099		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32730101	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730101		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730106	401	NA			24"				Yes		Bennett, Steve	clean_complete	08/29/2018	
32730107	507	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730107		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32730108	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730108		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730109	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730109		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730114		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32730115	507	NA			3"				No		Bennett, Roy	inspected_ok	06/15/2018	
32730115		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730116	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730116		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730117	401	NA			2"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730118	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730118		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730119	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730121	401	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730121		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730123	507	NA			1"				Yes		Bennett, Roy	inspected_ok	06/19/2018	
32730124	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730124		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730125	507	NA			1"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730125		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32730126	401	NA			4"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730126		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32730127	401	NA			3"				No		Bennett, Roy	inspected_ok	06/19/2018	
32730127		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731011	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731011		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731015	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731015		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731016	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731016		Catch Basin			4-6			6/29/17	Yes		20270	clean_complete	07/26/17	
32731017	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731017		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731020	401	NA			12"		Good		Yes	No	Dunaho, Milton	clean_complete	08/27/2018	
32731020		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731021	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731021		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731026	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731026		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731028	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731028		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731032	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731032		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731033	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32731033		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731048		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32731049	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731049		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731050	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731050		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731051	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731051		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731052	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731052		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731053	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731053		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731055	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731055		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731065	401	NA			8"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731065		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32731066	507	NA			8"		Good		No	No	Dunaho, Milton	inspected_ok	06/29/2018	
32731066		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731098	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731098		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	Broken lid
32731099	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731099		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731101	507	NA			12"	18	Good		Yes	No	Lyman, Brian	clean_complete	06/27/2018	
32731101		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731102	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731102		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731103	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731103		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731108	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731108		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32731109	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32731109		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32732010		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32732024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32732063	507	NA			8"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32732063		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733006	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733007	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733007		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733008	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733010	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733011	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733011		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733016	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733016		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733025	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733025		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733026	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733026		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733027	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733027		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733028	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733028		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733029	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32733029		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733030	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733030		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733032	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733032		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733033	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733033		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733034	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733034		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733035	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733035		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733036	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733036		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733037	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733037		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733040	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733040		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733043	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733043		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733044	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733044		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733050	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733050		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733051	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733051		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733052	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733052		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733053	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733053		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733054	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733054		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32733058		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733059	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733059		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733064	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733064		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733065	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733065		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733069	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733069		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733070	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733070		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733071	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733071		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733072	507	NA							Yes		Christ (Jr.), Jeffery	inspected_ok	09/19/2018	
32733072		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733076	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733076		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32733079	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733079		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733080	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733080		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733083	507	NA							Yes		Christ (Jr.), Jeffery	inspected_ok	09/19/2018	
32733083		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733092	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733092		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733093	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32733093		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733108	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733108		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733113	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733113		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733117		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733118	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733118		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733125	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733125		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733127	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733127		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733130	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733130		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733138	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733138		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733154	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733154		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733155	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733155		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733232		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733233	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32733233		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32733235	507	NA			12"		Good		Yes		Bennett, Steve	clean_complete	08/29/2018	
32733235		Manhole			6-8			6/29/17	Yes		30052	clean_complete	09/06/17	
32733236	401	NA			6"		Good		Yes	No	Bennett, Steve	clean_complete	08/29/2018	Witches hat fell into drain, and removed by vactor
32733236		Catch Basin			6-8			6/29/17	Yes	Yes		clean	6/29/17	Witches hat.
32734001	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734001		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734002	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734002		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734003	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734006	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734007	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734007		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734008	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734010	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734021	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734021		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734023	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734023		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734024	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734032	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734032		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734045	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734045		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32734047	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734047		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734049	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734049		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734050	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734050		Catch Basin			6-8		Immediate	6/29/17	Yes		30052	clean_complete	6/29/17	Basin inhaling, causing sinkhole.

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32734056	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734056		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734057	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734057		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734058	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734058		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734059	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734059		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734060	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734060		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32734066	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734066		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734072	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734072		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734073	401	NA			8"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734073		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734074	401	no asbuilts			1"				No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734074		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734075	401	no asbuilts			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734075		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734076	401	no asbuilts			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734076		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734082	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734082		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734083	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734083		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734085	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734085		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734086	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734086		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734093	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734093		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734094	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734094		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734099	401	no asbuilts			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734099		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734101	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734101		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734109	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734109		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734110	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734110		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734112	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734112		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734113	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734113		Manhole			6-8			6/29/17	Yes			clean	6/29/17	Behind house. Unable to clean.
32734114	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734114		Catch Basin			6-8			6/29/17	Yes		30052	clean_complete	09/06/17	
32734116	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734116		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734120	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734120		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734121	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	
32734121		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734128	401	NA			4"				No		Bennett, Roy	inspected_ok	06/20/2018	
32734128		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32734140	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/27/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32734140		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32735019	401	NA			1"				No		Bennett, Roy	inspected_ok	06/20/2018	
32735019		Catch Basin			8-10			6/29/17	Yes		30052	clean_complete	09/06/17	
32737003	401	in drainage ditch?			None		Good		No	No	Amell, Mark	inspected_ok	06/20/2018	
32737003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	in drainage ditch?
32829001		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32829002	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32829002		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32829007		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32829008	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32829008		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32829015		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32829016	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32829016		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830002	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830002		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830006	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830008	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830014	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830014		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830018	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830020	507	NA			4"		Good		Yes	No	Knoedler, Shawn	inspected_ok	09/27/2018	No access - 9/27/18 no access, in fenced back yard, no access for the truck
32830020		Manhole			4-6			6/29/17	Yes			clean	6/29/17	Access from trail. 39021 cannot fit.
32830021		Manhole			4-6			6/29/17	Yes			clean	6/29/17	Access from trail.
32830022	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830022		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830023	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830023		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830025	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830025		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830026	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830026		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32830063	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32830063		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831003	401	NA			6"		Good		Yes		Dunaho, Milton	inspected_ok	08/29/2018	
32831003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831006	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831006		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831008	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831008		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831009	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831009		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831011	507	NA			12"		Good		No		Bennett, Steve	clean_complete	08/01/2018	
32831011		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32831012	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831012		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831014	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831014		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831015	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831015		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831016	401	NA			None				Yes		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831016		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831018	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32831019	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831019		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831020	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831020		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831021	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831021		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831022	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831022		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831032	507	NA			3"				Yes		Bennett, Steve	clean_complete	08/29/2018	
32831032		Manhole			2-4"			6/29/17	No			inspected_ok	6/29/17	
32831034	401	NA			3"				Yes		Bennett, Steve	clean_complete	06/14/2018	
32831034		Catch Basin			2-4"			6/29/17	No			inspected_ok	6/29/17	
32831035	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831035		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831037	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831037		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32831040	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32831040		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832001	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832007	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832007		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832008	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832016	507	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832016		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832017	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832017		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832018	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832019	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832019		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832020	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832020		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32832021	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832023	401	NA			8"		Good				Christ (Jr.), Jeffery	clean_complete	08/28/2018	
32832024	507	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832026	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832028	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832029	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832036	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832042	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832056	507	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32832056		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833001	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833001		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833002	401	NA			2"	12	Good		Yes		Christ (Jr.), Jeffery	clean_complete	06/14/2018	
32833002		Catch Basin			2-4"			6/29/17	No			inspected_ok	6/29/17	
32833003	401	NA			3"		Good		Yes	No	Butler, Ron	clean_complete	07/27/2018	
32833003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833004	401	NA			2"				No		Bennett, Steve	clean_complete	08/01/2018	
32833004		Catch Basin			2-4"			6/29/17	Yes		30052	clean_complete	09/06/17	
32833005	401	NA			3"				No		Bennett, Steve	clean_complete	08/01/2018	
32833006	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	07/27/2018	
32833006		Catch Basin			2-4"			6/29/17	Yes		30052	clean_complete	09/06/17	
32833010	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833011	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833011		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32833015	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833015		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833016	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833016		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833019	401	NA			3"		Good		Yes	No	Butler, Ron	clean_complete	07/26/2018	
32833019		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833022	401	NA			1"		Good		Yes	No	Butler, Ron	clean_complete	06/14/2018	
32833022		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833024	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	07/26/2018	
32833024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833025	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	06/14/2018	
32833025		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833028	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833028		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833030	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	06/14/2018	
32833030		Catch Basin			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
32833031	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	07/27/2018	
32833031		Catch Basin			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
32833039	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833039		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32833057	401	NA			2"		Good		Yes	No	Butler, Ron	clean_complete	07/26/2018	
32833057		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833060	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833060		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833061	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833061		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833062	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833062		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833063	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833063		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833066	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833066		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833067	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833067		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833068	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833068		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833074	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833074		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833083		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833088	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833088		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32833091	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833091		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833093	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833093		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833095		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833098	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833098		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32833099	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32833099		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834001	507	NA			3"				Yes		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834001		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834002	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834002		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834003	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834003		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834006	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32834006		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834008	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834012	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834012		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834014	401	NA							No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834014		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834020	401	NA			12"	12	Good		Yes		Bell, Brian, Brian	clean_complete	07/25/2018	
32834020		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834024	401	NA			10"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834026	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834026		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834027	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834027		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834029	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834029		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834032	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834032		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834034	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834034		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834036	507	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834036		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834037	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834037		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834041	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834041		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834042	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834042		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834056	507	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834056		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834059	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834059		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834060	401	NA			6"				No		Bennett, Steve	clean_complete	08/01/2018	
32834060		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834061	401	NA			2"				No		Butler, Ron	clean_complete	08/01/2018	
32834061		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834062	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834062		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834064	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834064		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834065	507	NA			None				Yes		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834065		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32834066	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834066		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32834070	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834070		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834071	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834071		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834075	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834075		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834076	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834076		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834080	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834080		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834084	507	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834084		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32834085	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834085		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834089	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834089		Catch Basin			10-12			6/29/17	Yes		30052	clean_complete	6/29/17	
32834091	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834091		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32834092	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834092		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32834095	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834095		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834096	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834096		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834099	401	NA			3"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834099		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834100	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834100		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834110	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834110		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	Has another catch basin across the street not on map
32834111	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834111		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834112	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834112		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834113	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834113		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834114	401	NA			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834114		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834116	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834116		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834138	401	NA			1"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834138		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834139	401	Catch Basin Outlet			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834139		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	Catch Basin Outlet; Dry/no water
32834140	401	bund 2008 Vactor book			6"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834140		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834142	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834142		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32834144	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32834144		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835008	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835011	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835011		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835014	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835014		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835015	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835015		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835017	401	NA			1"		Good		Yes	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835017		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835018	401	NA			1"		Good		No	No		inspected_ok	06/14/2018	
32835018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835021	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835021		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835022	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835022		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32835026	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835026		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835034	401	NA			8"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32835034		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32835035	401	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32835035		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835036	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835036		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32835037	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835037		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32835038	401	NA			8"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32835038		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835039	507	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835039		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835041	507	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835041		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835051	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835051		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835057	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835057		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835060	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835060		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835074	507	NA			3"		Good		No	No	Bennett, Steve	clean_complete	08/01/2018	
32835074		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835075	507	NA			4"		Good		No	No	Butler, Ron	clean_complete	08/01/2018	
32835075		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835076	401	NA		18"	8"	18	Good			No	Amell, Mark	clean_complete	10/09/2018	crane truck 10/5/18 tried everything. Mechanics put presser and heat. Didn't
32835077	401	NA		12"	5"	18	Good			No	Dunaho, Milton	clean_complete	06/14/2018	Mechanics put presser and heat. Didn't move. Need loader or crane for this..
32835269	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835269		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32835270	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32835270		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32836003		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32836004		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32836005	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836005		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32836006	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836006		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32836007	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836007		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32836008	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836008		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32836009	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836009		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32836010	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/15/2018	
32836010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932001	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932001		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932002	401	NA			2"		Poor		No	No	Dunaho, Milton	inspected_ok	06/14/2018	Broken concrete in front of face
32932002		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932003	507	NA			6"		Good		No	No	Bennett, Steve	clean_complete	08/01/2018	
32932003		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
32932004	401	NA			5"				Yes		Butler, Ron	clean_complete	08/01/2018	
32932004		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32932007	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932007		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932008	507	NA			1"		Good		Yes	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932008		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	Dry catch basin
32932009	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932009		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32932010	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932010		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932011	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932011		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932013	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932013		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932014	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
32932014		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932015	507	NA			1"		Good		Yes	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932015		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932017	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932017		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932023	401	NA		8"	4"	12	Good		Yes	No	Dunaho, Milton	inspected_ok	10/04/2018	on grass
32932024	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932025	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932025		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32932029	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32932029		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933001	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32933001		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32933003	401	NA			5"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32933003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933004	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32933004		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933005	507	NA			None		Poor		Yes	No	Lyman, Brian	inspected_ok	08/28/2018	Stopped by again on 8-7-18 and still has a vehicle in front of drain.
32933005		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933006	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32933006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933008	401	NA			1"		Good			No	Christ (Jr.), Jeffery	inspected_ok	08/07/2018	
32933008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933015	507	NA			3"		Good			No	Christ (Jr.), Jeffery	inspected_ok	08/07/2018	
32933015		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933016	401	NA			12"		Good				Christ (Jr.), Jeffery	clean_complete	09/19/2018	
32933016		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32933017	401	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32933017		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933034	507	NA			1"		Poor		No	No	Dunaho, Milton	inspected_ok	06/14/2018	Broken grate
32933034		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32933036	401	NA			3"				No	No	Christ (Jr.), Jeffery	inspected_ok	08/30/2018	
32933036		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	Broken man hole
32934003	401	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934004	401	NA			1"		Good		No	No	Butler, Ron	clean_complete	07/26/2018	
32934004		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934005	507	NA			6"		Good		Yes	No	Butler, Ron	clean_complete	07/26/2018	
32934005		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32934011	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934011		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934014	507	NA			4"				Yes	No	Dunaho, Milton	clean_complete	06/14/2018	
32934014		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32934018	401	NA			2"		Good		No	No	Butler, Ron	clean_complete	07/26/2018	
32934018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934020		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32934021	401	NA			6"	12	Good		Yes	No	Dunaho, Milton	clean_complete	06/14/2018	
32934021		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32934023		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32934024	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934052	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934056	507	NA			6"	12	Good		Yes	No	Bell, Brian, Brian	clean_complete	07/25/2018	
32934056		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32934057	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934059	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934059		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934060	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934061	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934061		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934062	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934063	507	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934065	507	NA			6"	12	Good		Yes	No	Dunaho, Milton	clean_complete	07/25/2018	
32934065		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	Broken drain face
32934079	507	NA			2"				No	No	Dunaho, Milton	clean_complete	06/14/2018	
32934079		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934080	507	NA			2"				No	No	Dunaho, Milton	clean_complete	06/14/2018	
32934080		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934096	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934096		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934105		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934106	507	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934106		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934109	401	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934109		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934126	401	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934126		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934128	401	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32934128		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32934140	401	NA			6"	12	Good		Yes	No	Dunaho, Milton	clean_complete	06/14/2018	
32934140		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32934142	507	NA			6"		Good		Yes	No	Butler, Ron	clean_complete	06/14/2018	
32934142		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
32934146	401	NA			6"	12	Good		Yes	No	Bell, Brian, Brian	clean_complete	07/25/2018	
32934146		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32934147	401	NA			6"	12	Good		Yes	No	Bell, Brian, Brian	clean_complete	07/25/2018	
32934147		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32934162	401	NA			6"	12	Good		Yes	No	Bell, Brian, Brian	clean_complete	07/25/2018	
32934162		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935004	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935004		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935005	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935005		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935006	401	NA			3"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935007	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935012	401	NA			6"		Good		Yes	No	Bennett, Steve	clean_complete	08/01/2018	
32935012		Catch Basin			6-8			6/29/17	No			inspected_ok	6/29/17	
32935013	401	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935013		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935014	401	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935014		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935016	401	NA			1"		Good		No	No	Van Fleet, Myhi	inspected_ok	06/14/2018	
32935016		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935021	401	NA			5"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935021		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32935022	401	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935022		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935023	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935023		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935024	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935024		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935025	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935025		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935036	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935036		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32935037	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935037		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935038	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935038		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935042	401	NA			3"		Good		No	No	Van Fleet, Myhi	inspected_ok	06/14/2018	
32935042		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32935044	401	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935044		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32935046	401	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935046		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935050	401	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935050		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935051	401	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935051		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935053	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935053		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935054	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935054		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935058	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935058		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935059	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935059		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935061	507	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935061		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32935062	507	NA			8"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935062		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935063	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935063		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935064	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935064		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935065	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935065		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935066	507	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935066		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935067	507	NA			4"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935067		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935068	507	NA			8"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935068		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935069	507	NA			4"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935069		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935070	507	NA			6"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935070		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32935071	507	NA			8"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935071		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
32935074	401	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935075	507	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935076	401	NA			2"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32935076		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935077	401	NA			1"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935077		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935127	507	NA			1"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935127		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32935128	401	NA			6"		Good		No	No	Dunaho, Milton	clean_complete	06/14/2018	
32935128		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935129	401	NA			3"		Good		No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935129		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32935194	507	NA			2"				No	No	Dunaho, Milton	inspected_ok	06/14/2018	
32935194		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936002	401	NA			18"		Good		No	No	Christ (Jr.), Jeffery	clean_complete	06/14/2018	
32936002		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
32936003	401	NA			18"		Good		Yes	No	Christ (Jr.), Jeffery	clean_complete	06/14/2018	
32936003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936006	401	NA			2"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936006		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936007	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936007		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936008	401	NA			4"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936008		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
32936009	507	NA			8"				No	No	Christ (Jr.), Jeffery	clean_complete	06/14/2018	
32936009		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
32936010	401	NA			8"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936011	401	NA			None				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936011		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936012	401	NA			12"				No		Christ (Jr.), Jeffery	inspected_ok	06/14/2018	
32936012		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
32936013	401	NA			18"		Good		No		Christ (Jr.), Jeffery	clean_complete	06/14/2018	
32936013		Catch Basin			8-10			6/29/17	No			inspected_ok	6/29/17	
33033003	401	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033004	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033004		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033008	401	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033008		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033009	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033009		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033010	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033010		Manhole			0-2"			6/29/17	Yes			inspected_ok	6/29/17	
33033011	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033011		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033012	507	NA							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033012		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33033091	401	talled by St. Maint 2011							No		Van Fleet, Myhi	inspected_ok	06/13/2018	
33033091		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536005	507	NA							No	No	Bennett, Steve	inspected_ok	08/07/2018	
33536005		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
33536010	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536010		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536014	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536014		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536015	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536015		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536016	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536016		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
33536018	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536018		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536019	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536019		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536022	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536022		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536023	507	NA							No	No	Bennett, Steve	inspected_ok	08/07/2018	
33536023		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33536025	507	NA			None		Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536025		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
33536027	507	NA			None		Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33536027		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
33536028	507	NA			None		Good		No	No	Knoedler, Shawn	clean_complete	07/23/2018	
33536028		Manhole			2-4			6/29/17	No			inspected_ok	6/29/17	
33537001	507	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33537001		Manhole			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
33537002	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33537002		Catch Basin			2-4			6/29/17	No			inspected_ok	6/29/17	
33537003	507	NA							No		Knoedler, Shawn	inspected_ok	08/07/2018	
33537003		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	Witches hat
33537009	507	NA			None		Good		No	No	Mathis, Linus	inspected_ok	07/23/2018	
33537009		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33537012	507	NA							No		Knoedler, Shawn	inspected_ok	08/07/2018	
33537012		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33537013		Catch Basin			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
33537042		Manhole			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
33537043		Manhole			2-4			6/29/17	Yes		30052	clean_complete	09/06/17	
33537065	401	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33537065		Catch Basin			4-6			6/29/17	No			inspected_ok	6/29/17	
33537066	507	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33537066		Manhole			4-6			6/29/17	No			inspected_ok	6/29/17	
33537071	507	NA							No		Bennett, Steve	inspected_ok	08/07/2018	
33537071		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33537076	507	NA					Good		No	No	Mathis, Linus	clean_complete	07/23/2018	
33537076		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
33637003	401	NA							Yes		Knoedler, Shawn	clean_complete	08/07/2018	
33637003		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33637013	401	NA			4"		Good		No		Bennett, Steve	clean_complete	08/07/2018	
33637013		Catch Basin			0-2"			6/29/17	No			inspected_ok	6/29/17	
33637014	507	NA							Yes		Knoedler, Shawn	clean_complete	08/07/2018	
33637014		Manhole			0-2"			6/29/17	No			inspected_ok	6/29/17	
	401	6			6"	12	Good		Yes	No	Contractor	clean_complete	05/17/2018	
	401	6			10"	12	Good		Yes	No	Contractor	clean_complete	05/20/2018	
	507			12"	6"	12	Good				Bell, Brian, Brian	clean_complete	09/26/2018	
32329020		Manhole	Type 1	12-14"	12-14	12	Good	08/26/17	Yes	No	Contractor	clean_complete	08/26/17	
32329041		Catch Basin	Type 1	14-16"	0-2"	12	Good	08/26/17	Yes	No	Contractor	clean_complete	08/26/17	
32329078		Catch Basin	Type 1	16-18"	0-2"	15	Good	08/26/17	Yes	No	Contractor	clean_complete	08/26/17	Installed: 2016
32333003		Catch Basin			0-2"				No		Contractor	inspected_ok		
32333004		Catch Basin								Yes	Contractor			Witches hat. Not inspected
32333005		Catch Basin			2-4			07/20/17			62187	clean_complete	07/20/17	
32333011		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333015		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333016		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333020		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333022		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333046		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333053		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Back	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32333054		Catch Basin			4-6			2017	Yes		Contractor	clean		
32333055		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333056		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333058		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333059		Catch Basin								Yes	Contractor			Witches hat. Not inspected
32333060		Manhole			6-8			2017	No		Contractor	inspected_ok		
32333061		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333063		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333064		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333065		Manhole								Yes	Contractor			Witches hat. Not inspected
32333072		Catch Basin								Yes	Contractor			Witches hat. Not inspected
32333087		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333088		Catch Basin						2017			Contractor			Does not exist (abandoned?)
32333093		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333098		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333102		Manhole								Yes	Contractor			Witches hat. Not inspected
32333103		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333104		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333105		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333108		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333109		Manhole								Yes	Contractor			Witches hat. Not inspected
32333112		Catch Basin									Contractor			Couldn't find (non-existent?)
32333113		Catch Basin									Contractor			Couldn't find(non-existent?)
32333140		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333141		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333142		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333143		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333144		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333145		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333148		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333149		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333150		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333151		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333152		Manhole			0-2"			2017	No		Contractor	inspected_ok		Catchbasin Manhole covered by boulders and dirt. Needs uncovered
32333153		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333154		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333155		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333156		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333158		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333160		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333170		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333206		Manhole			6-8			2017	No		Contractor	inspected_ok		
32333207		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333228		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32333229		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333230		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32333231		Manhole			6-8			2017	No		Contractor	inspected_ok		
32333255		Manhole			0-2"			2017	Yes		Contractor	clean		
32334005		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334006		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334007		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334008		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334035		Catch Basin									Contractor			Witches hat on it
32334037		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334054		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334055		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334061		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32334062		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334084		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334101		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334102		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334104		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334107		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334108		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334112		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334113		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334114		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334119		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334120		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334123		Manhole									Contractor			
32334125		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334126		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334129		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334133		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334136		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334137		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334138		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334139		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334140		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334141		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334142		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334147		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334149		Catch Basin	Type 1	8-10"	0-2"	12		2017			Contractor	inspected_ok		
32334150		Catch Basin									Contractor			
32334151		Catch Basin	Type 1	8-10"	4-6	12		2017			Contractor	clean		
32334152		Catch Basin	Type 1	8-10"	0-2"	12		2017			Contractor	inspected_ok		
32334153		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334155		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334156		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334157		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334158		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334159		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334160		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334162		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334163		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334164		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334165		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334167		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334168		Catch Basin									Contractor			Can't locate? In the back yard possibly under shed
32334170		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334171		Catch Basin									Contractor			Witches hat, not inspected
32334176		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334177		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334178		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334184		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334185		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334187		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334188		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334191		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334193		Manhole			4-6			2017	No		Contractor	inspected_ok		
32334195		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334196		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334220		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334225		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32334228		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334229		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334230		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334233		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334235		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334236		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334237		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334238		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334239		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334240		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334241		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334244		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334245		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334246		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334247		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334248		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334251		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334252		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334253		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334254		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334255		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334256		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334257		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334258		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334312		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32334314		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32334532		Catch Basin			2-4			2017	No		Contractor	inspected_ok		
32335001		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335004		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335007		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335012		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335014		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335015		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335019		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335020		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335021		Catch Basin			0-2"				No		Contractor	inspected_ok		
32335026		Manhole						2017			Contractor	inspected_ok		Under construction witches hat
32335027		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335028		Catch Basin									Contractor	inspected_ok		Under construction
32335030		Manhole									Contractor	inspected_ok		Motor home covering could not check
32335031		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335036		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335037		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335039		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335042		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335044		Manhole									Contractor	inspected_ok		Under construction
32335045		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335049		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335050		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335055		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335060		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335061		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335062		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335064		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335073		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32335074		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335076		Manhole			0-2"			2017	No		Contractor	inspected_ok		

ARDSA Fill Rate Data

DRAIN_ID	SUBTYPE	SubType	Structure_Type	Sump_Depth	Material_Depth	Outfall_Size	Overall_Condition	Date_Inspected	Basin_Cleaning_Required	Go_Backs	Cleaning_Employee	Inspect_Status	Date_Cleaning	Field_Notes
32335153		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32335154		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32336001		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32336002		Manhole									Contractor	inspected_ok		Witches hat
32336003		Manhole			0-2"			2017	No		Contractor	inspected_ok		
32336005		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32336006		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32336008		Catch Basin			0-2"			2017	No		Contractor	inspected_ok		
32336009		Catch Basin			6-8			07/20/17	No		62187	clean_complete	07/20/17	
32336010		Catch Basin			0-2"			07/20/17	No		Contractor	inspected_ok	07/20/17	
32336011		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336012		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336015		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336016		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336017		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336018		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336019		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336020		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336021		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336231		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336232		Manhole			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336235		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336236		Catch Basin			0-2"			07/20/17	No			inspected_ok	07/20/17	
32336239		Manhole			6-8			07/20/17	No			inspected_ok	07/20/17	
32424035		Manhole	Type 2	20-22"	6-8	18	Good	10/31/17	Yes	No		clean_complete	10/31/17	Instal: 2016
32424036		Catch Basin	Type 1	16-18"	2-4	12	Good	10/31/17	Yes	No		clean_complete	10/31/17	Instal: 2016
32427007		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32427053		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32427100		Manhole			4-6			09/19/17	No			inspected_ok	09/19/17	
32427101		Catch Basin			2-4			09/19/17	No			inspected_ok	09/19/17	
32427163		Catch Basin			0-2"			09/19/17	No			inspected_ok	09/19/17	
32428499		Manhole			0-2"			09/19/17	No			inspected_ok	09/19/17	
32433133		Manhole												
32433134		Catch Basin												
32433135		Catch Basin	Type 2	8-10"	6-8	12	Good	09/19/17			24417	clean_complete	09/19/17	
32433176		Catch Basin	Type 1	8-10"	6-8	12		09/19/17				clean	09/19/17	